

# Inventor Shortcut Keys.

## General Shortcuts

	<b>Shortcut Keys</b>
<b>Copy</b>	<b>Ctrl + C</b>
<b>Select all</b>	<b>Ctrl + A</b>
<b>Find</b>	<b>Ctrl + F</b>
<b>New File</b>	<b>Ctrl + N</b>
<b>Open file</b>	<b>Ctrl + O</b>
<b>Print</b>	<b>Ctrl + P</b>
<b>Save</b>	<b>Ctrl + S</b>
<b>Cut</b>	<b>Ctrl + X</b>
<b>Redo</b>	<b>Ctrl + Y</b>
<b>Undo</b>	<b>Ctrl + Z</b>
<b>Delete</b>	<b>Delete</b>

<b>Rename</b>	<b>F2</b>
<b>Exit</b>	<b>Quit</b>

## Function key

<b>Action</b>	<b>Shortcut Keys</b>
<b>Help</b>	<b>F1</b>
<b>Pan</b>	<b>F2</b>
<b>Zoom selected</b>	<b>F3</b>
<b>Rotate</b>	<b>F4</b>
<b>Previous view</b>	<b>F5</b>
<b>Home view</b>	<b>F6</b>
<b>Slice graphics</b>	<b>F7</b>
<b>Show all constrains</b>	<b>F8</b>
<b>Hide all constrains</b>	<b>F9</b>

<b>Sketch visibility</b>	<b>F10</b>
--------------------------	------------

## View Shortcuts

<b>Action</b>	<b>Shortcut Keys</b>
<b>User work plane visibility</b>	<b>Alt + ]</b>
<b>User work points visibility</b>	<b>Alt + .</b>
<b>User work axes visibility</b>	<b>Alt + /</b>
<b>Origin points visibility</b>	<b>Ctrl + .</b>
<b>Origin plane visibility</b>	<b>Ctrl + ]</b>
<b>Origin axes visibility</b>	<b>Ctrl + /</b>
<b>Switch screen</b>	<b>Ctrl + 0</b>
<b>Degrees of freedom</b>	<b>Ctrl + Shift + E</b>

<b>IMate Glyph</b>	<b>Ctrl + Shift + Q</b>
<b>Steering wheels</b>	<b>Ctrl + W</b>
<b>Zoom selected</b>	<b>End</b>
<b>Zoom all</b>	<b>Home</b>
<b>Look at a selected entity</b>	<b>Page Up</b>
<b>Zoom window</b>	<b>Shift + F3</b>
<b>Next view</b>	<b>Shift + F5</b>

## Cable and Harness Hotkeys

<b>Action</b>	<b>Shortcut Keys</b>
<b>Automatic route</b>	<b>AR</b>
<b>Check bend radius</b>	<b>BR</b>
<b>Broken sketch entity</b>	<b>BS</b>

<b>Connector authoring</b>	<b>CA</b>
<b>Create cable</b>	<b>CC</b>
<b>Create fold</b>	<b>CF</b>
<b>Create ribbon cable</b>	<b>CR</b>
<b>Create segment</b>	<b>CS</b>

## Sketch Shortcuts

<b>Action</b>	<b>Shortcut Keys</b>
<b>Equal</b>	<b>=</b>
<b>Ortho mode</b>	<b>Ctrl + R</b>
<b>Dynamic dimension</b>	<b>Ctrl + D</b>
<b>Snap object</b>	<b>Ctrl + Shift + P</b>
<b>Infer constraints</b>	<b>Ctrl + I</b>

## Tools Shortcuts

<b>Action</b>	<b>Shortcut Keys</b>
Macros	Alt + F8
Visual Basic Editor	Alt + F11
Switch browser pane forward	Alt + A
Switch Browser pane backward	Alt + S
Cancel	Esc

## Work features Shortcuts

<b>Action</b>	<b>Shortcut keys</b>
Grounded work point	;
Work axis	/
Work plane	]
Work point	.

## Annotation Hotkeys

<b>Action</b>	<b>Shortcut keys</b>
<b>Caterpillar</b>	<b>CAT</b>
<b>Centerline</b>	<b>CL</b>
<b>Datum identifier</b>	<b>DM</b>
<b>End fill</b>	<b>EF</b>
<b>feature control frame</b>	<b>F</b>
<b>Feature identifier symbol</b>	<b>FI</b>
<b>Hole table features</b>	<b>HTF</b>
<b>Hole table selection</b>	<b>HTS</b>
<b>Leader text</b>	<b>LE</b>
<b>Parts list</b>	<b>PL</b>
<b>Revision tag</b>	<b>RT</b>
<b>Surface texture symbol</b>	<b>ST</b>

<b>Revision table</b>	<b>RTB</b>
<b>Symbols</b>	<b>SY</b>
<b>Text</b>	<b>T</b>
<b>Table</b>	<b>TB</b>

## Assembly Shortcuts

<b>Action</b>	<b>Shortcut keys</b>
<b>Mate Constarint</b>	<b>Alt + cursor</b>
<b>Replace</b>	<b>Ctrl + H</b>
<b>Promote</b>	<b>Shift + Tab</b>
<b>Open drawing</b>	<b>Ctrl + D</b>
<b>Toggle transparent state</b>	<b>Alt + T</b>
<b>Visibility</b>	<b>Alt + V</b>

## Others Autodesk Inventor Shortcuts

<b>Action</b>	<b>Shortcut keys</b>
New sheet	Ctrl + Shift + N
Leader text	Ctrl + Shift + T
Create drawing view	Alt + C
Chamfer	Ctrl + Shift + K
Loft	Ctrl + Shift + L
Mirror	Ctrl + Shift + M
Circular pattern	Ctrl + Shift + O
Rectangular pattern	Ctrl + Shift + R

**Sweep**

**Ctrl + Shift +  
S**

•